

## Jacket stripper for POF cables

### 1 General \_\_\_\_\_

This tool allows a perfect stripping of POF cables with jacket outer diameter up to 6mm.

### 2 Features \_\_\_\_\_

- avoids abrasion, carving and notching of cable
- enables clean removing of cable jacket with outer diameter 1.5/2.5/4.0/6.0mm and a fiber core Ø up to 1mm
- quick replacement of blades
- rugged plier with ergonomic and insulated handles
- flexible stripped cables stay round
- suitable for fibers according IEC 60793-2-40



Pic. 1 Jacket stripper

### 3 Operating instruction \_\_\_\_\_


- put the cable into required blade cavity
- pretension the plier, straighten out the stripping area and latch the plier fully to strip the jacket



Pic. 2 Cavities

### 4 Ordering information \_\_\_\_\_

<b>Specification</b>	<b>Part no.</b>
Stripping plier	910AZ00100001



Pic. 3 Dimensions

The information released by Ratioplast-Optoelectronics GmbH in this data sheet is believed to be accurate and reliable. However, no responsibility is assumed by Ratioplast-Optoelectronics GmbH for its use. Ratioplast-Optoelectronics GmbH reserves the right to change circuitry and specifications at any time without notification to the customer.